| Field | Report | No. | 14 |
|-------|--------|-----|----|
|-------|--------|-----|----|

| • | | | | | |
|----------------|------------------|---|-----------------|-----------------|--|
| | Client: | | | Town of Sudbury | |
| | Project Name: | Sudbury-Hudson Transmission Reliability | | | |
| | Inspector: | | | Jeffrey Polidor | |
| | Project No: | | | 22012F | |
| Horsley Witten | Inspection Date: | 9/06/23 | Arrival Time: | 8:00 AM | |
| Group, Inc. | Weather: | Sunny, 85°F | Departure Time: | 11:30 AM | |
| | | | | | |
| | | | | | |

Contractor(s) equipment:

Excavator (2) Dumpster (2)

Dumpster (2) Roller (1)

Reference Plan:

Sudbury to Hudson

115kV Underground Transmission Line

Sudbury - Hudson, MA Date: November 16, 2018

WORK UNDERWAY:

| Erosion Control Installation | \boxtimes |
|------------------------------|-------------|
| Clearing/Grubbing | |
| Excavation/Fill/Compaction | \boxtimes |
| Road Subbase Installation | |
| Gravel Base Installation | |
| Pavement/Binder Installation | |
| Water Installation | |
| Gas/Electric/Telephone | |
| Installation | |

| Drainage Installation | \boxtimes |
|-------------------------|-------------|
| Wastewater Construction | |
| Sidewalk Construction | |
| Final Grading | |
| Surface Stabilization | |
| Monument Installation | |
| Cleanup | |
| Other: | |

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

Photos Taken: Yes No

General Notes/Comments:

On September 6, 2023, Horsley Witten Group, Inc. (HW) performed a site visit along the Eversource transmission line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion control installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 7-9, 12, and 14.
- A manhole was being installed in between segment 8 and segment 9 (Photo 1)
- Silt fence has a broken stake along segment 10 (Photo 2).
- Sediment has tracked into the road from gravel construction entrance STA 361+00 (Photo 3).
- Silt fence has a broken stake along segment 11 in two places (Photo 3).
- Silt fence is under a boulder at a point along segment 13 (Photo 4).
- Silt fence has a broken stake at Bridge 127 along segment 13 (Photo 5)
- Form, rebar, and pour abutment wall was being installed at Bridge 127 (Photo 6).

Action Items:

1. Repair silt fence and filter tube as noted above.

Field Report No. 14 page 2

Inspector's signature:

Date: 9/6/23

Jeffrey Polidor

Survey-GIS Technician

Distribution:

Town: Lori Capone Shawna Risotti

Epsilon Associates: Marc Bergeron

Horsley Witten Group: Janet Carter Bernardo, P.E.

Jeffrey Polidor

caponel@sudbury.ma.us RisottiS@sudbury.ma.us

mbergeron@epsilonassociates.com

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

jbernardo@horsleywitten.com jolidor@horsleywitten.com

PHOTOS:



Photo 1: Manhole installation between segment 8 and segment 9. Photo taken on 9/06/23

Field Report No. 14 page 3



Photo 2: Broken stake in the silt fence along segment 10. Photo taken on 9/06/23



Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660

Photo 3: Sediment in the road from gravel construction entrance STA 361+00. Photo taken on 9/06/23

Field Report No. 14

Phone: (508) 833-6600

Phone: (857) 263-8193 Phone: (401) 272-1717

Phone: (603) 658-1660



Photo 4: Boulder on the silt fence along segment 13. Photo taken on 9/06/23



Photo 5: Broken stake in the silt fence near Bridge 127 along segment 13. Photo taken on 9/06/23

Field Report No. 14

Phone: (508) 833-6600

Phone: (857) 263-8193

Phone: (401) 272-1717

Phone: (603) 658-1660



Photo 6: Form, rebar, and pour abutment wall being installed at Bridge 127. Photo taken on 9/06/23