

Horsley Witten Group, Inc.

Client:	Town of Sudbury
Project Name:	Sudbury-Hudson Transmission Reliability
Inspector:	Jeffrey Polidor
Project No:	22012F
Inspection Date: 3/14/23	Arrival Time: 7:00 AM
Weather: Light flurries, 30°F	Departure Time: 11:00 AM

Personnel on site: Marc Bergeron

Matt Lagoy Terry Ramborger

Reference Plan:

Sudbury to Hudson 115kV Underground Transmission Line Sudbury - Hudson, MA Date: November 16, 2018

Contractor(s) equipment:

Excavator (3) Dumpster (2)

WORK UNDERWAY:

Erosion Control Installation	
Clearing/Grubbing	
Excavation/Fill/Compaction	\boxtimes
Road Subbase Installation	
Gravel Base Installation	
Pavement/Binder Installation	
Water Installation	
Gas/Electric/Telephone	
Installation	

Drainage Installation		
Wastewater Construction		
Sidewalk Construction		
Final Grading		
Surface Stabilization		
Monument Installation		
Cleanup		
Other: Rail & Tie Removal	\square	

Photos Taken: Yes 🔀 No 🗌

General Notes/Comments:

On March 14, 2023, Horsley Witten Group, Inc. (HW) performed a site visit in Sudbury, MA. During the site visit HW walked all segments with erosion control installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working conditions.

- Silt fence has been installed and is operating properly along segments 7, 8, 9, 10, 11, 13 and 14 (Photos 1-3 and 5-9).
- Turbidity curtain, filter tubes, and silt fence have been installed at bridge 127 (Photo 2).
- Silt fence is partially installed along segment 12 (Photo 4).
- Filter tube has been installed and is operating properly along segment 9 (Photo 7).

/ol

Inspector's signature:

Date: 314/23

Jeffrey Polidor Survey-GIS Technician

Distribution:		
Town:	Lori Capone	caponel@sudbury.ma.us
	Adam Duchesneau	duchesneaua@sudbury.ma.us
Epsilon Associates:	Marc Bergeron	mbergeron@epsilonassociates.com
Horsley Witten Group:	Janet Carter Bernardo, P.E. Jeffrey Polidor	jbernardo@horsleywitten.com jolidor@horsleywitten.com

PHOTOS:



Photo 1: Silt fence operating properly along segment 14. Photo taken on 3/14/23

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 55 Dorrance Street, Suite 403, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



Photo 2: Turbidity curtain, filter tubes, and silt fence installed and operating properly at bridge 127.

Photo taken on 3/14/23



Photo 3: Silt fence operating properly along segment 13. Photo taken on 3/14/23

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 55 Dorrance Street, Suite 403, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



Photo 4: Silt fence operating properly along segment 12 while construction occurs. Photo taken on 3/14/23



Photo 5: Silt fence operating properly along segment 11. Photo taken on 3/14/23

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 55 Dorrance Street, Suite 403, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833



Photo 6: Silt fence operating properly along segment 10. Photo taken on 3/14/23



Photo 7: Silt fence and filter tube installed and operating properly along segment 9. Photo taken on 3/14/23



Photo 8: Silt fence operating properly along segment 8. Photo taken on 3/14/23



Photo 9: Silt fence operating properly along segment 7. Photo taken on 3/14/23

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 55 Dorrance Street, Suite 403, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833