



Horsley Witten Group, Inc.

Client: Town of Sudbury
 Project Name: Sudbury-Hudson Transmission Reliability
 Inspector: Jeffrey Polidor
 Project No: 22012F
 Inspection Date: 3/30/23 Arrival Time: 7:00 AM
 Weather: Clear, 35°F Departure Time: 10:30 AM

Personnel on site:

Marc Bergeron
 Matt Lagoy
 Ariel Leclerc

Reference Plan:

Sudbury to Hudson
 115kV Underground Transmission Line
 Sudbury - Hudson, MA
 Date: November 16, 2018

Contractor(s) equipment:

Excavator (2)
 Dumpster (1)

WORK UNDERWAY:

Erosion Control Installation	<input checked="" type="checkbox"/>
Clearing/Grubbing	<input type="checkbox"/>
Excavation/Fill/Compaction	<input checked="" type="checkbox"/>
Road Subbase Installation	<input type="checkbox"/>
Gravel Base Installation	<input type="checkbox"/>
Pavement/Binder Installation	<input type="checkbox"/>
Water Installation	<input type="checkbox"/>
Gas/Electric/Telephone Installation	<input type="checkbox"/>

Drainage Installation	<input type="checkbox"/>
Wastewater Construction	<input type="checkbox"/>
Sidewalk Construction	<input type="checkbox"/>
Final Grading	<input type="checkbox"/>
Surface Stabilization	<input type="checkbox"/>
Monument Installation	<input type="checkbox"/>
Cleanup	<input type="checkbox"/>
Other: Rail & Tie Removal	<input type="checkbox"/>

Photos Taken: Yes No

General Notes/Comments:

On March 30, 2023, Horsley Witten Group, Inc. (HW) performed a site visit in Sudbury, MA. During the site visit HW walked all segments with erosion control installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working conditions.

- Silt fence has been installed and is functioning properly along segments 7, 9, 10, 11, 13 and 14 (Photos 1, 3, 5-7, and 9).
- Stakes in the silt fence were broken and need to be replaced along segments 8 and 12, as well as at construction entrance STA476+00. (Photos 2, 4, and 8).
- Silt fence along segment 12 also has noticeable sagging in close proximity to Hop Brook (Photo 4).

Inspector's signature: Jeffrey Polidor
 Jeffrey Polidor

Date: 3/30/23

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
 112 Water Street, 6th Floor, Boston, MA 02109
 55 Dorrance Street, Suite 403, Providence, RI 02903
 113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
 Phone: (857) 263-8193
 Phone: (401) 272-1717
 Phone: (603) 658-1660

Survey-GIS Technician

Distribution:

Town:	Lori Capone	caponel@sudbury.ma.us
	Adam Duchesneau	duchesneua@sudbury.ma.us
Epsilon Associates:	Marc Bergeron	mbergeron@epsilonassociates.com
Horsley Witten Group:	Janet Carter Bernardo, P.E.	jbernardo@horsleywitten.com
	Jeffrey Polidor	jolidor@horsleywitten.com

PHOTOS:



Photo 1: Silt fence functioning properly along segment 14.
Photo taken on 3/30/23

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
55 Dorrance Street, Suite 403, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660



Photo 2: Broken silt fence stake that needs to be replaced at construction entrance (SUB STATION).

Photo taken on 3/30/23



Photo 3: Silt fence and filter tubes functioning properly along segment 13.

Photo taken on 3/30/23

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
55 Dorrance Street, Suite 403, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660



Photo 4: Broken silt fence stake and notable sagging in the fence along segment 12.
Photo taken on 3/30/23



Photo 5: Silt fence functioning properly along segment 11.
Photo taken on 3/30/23

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
55 Dorrance Street, Suite 403, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660



Photo 6: Silt fence functioning properly along segment 10.
Photo taken on 3/30/23



Photo 7: Silt fence functioning properly along segment 9.
Photo taken on 3/30/23

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
55 Dorrance Street, Suite 403, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660



Photo 8: Broken stake in the silt fence along segment 8.
Photo taken on 3/30/23



Photo 9: Silt fence functioning properly at Hop Brook Bridge along segment 7.
Photo taken on 3/30/23

Horsley Witten Group, Inc.

90 Route 6A, Sandwich, MA 02563
112 Water Street, 6th Floor, Boston, MA 02109
55 Dorrance Street, Suite 403, Providence, RI 02903
113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600
Phone: (857) 263-8193
Phone: (401) 272-1717
Phone: (603) 658-1660