

Horsley Witten Group, Inc.

Client:			Town of Sudbury
Project Name:		Sudbury-Hudson	Transmission Reliability
Inspector:			Jeffrey Polidor
Project No:			<u>22012F</u>
Inspection Date:	11/15/24	Arrival Time:	10:00 AM
Weather:	Clear, 45°F De	eparture Time:	<u>1:00 PM</u>

Contractor(s) equipment: Pickup Truck (1) Reference Plan: Sudbury to Hudson 115kV Underground Transmission Line Sudbury - Hudson, MA Date: November 16, 2018

WORK UNDERWAY:

Erosion Control Installation	\square
Clearing/Grubbing	
Excavation/Fill/Compaction	
Road Subbase Installation	
Gravel Base Installation	
Pavement/Binder Installation	
Water Installation	
Gas/Electric/Telephone	
Installation	

Drainage Installation	
Wastewater Construction	
Sidewalk Construction	
Final Grading	
Surface Stabilization	
Monument Installation	
Cleanup	
Other:	

Photos Taken: Yes 🔀 No 🗌

General Notes/Comments:

On November 15, 2024, Horsley Witten Group, Inc. (HW) staff performed a site visit along the Eversource Transmission Line corridor in Sudbury, MA. During the site visit HW walked all segments with erosion controls installed (7-14) and confirmed erosion control practices at the gravel construction entrances are still in working condition.

- Silt fence and filter tube are functioning properly along segments 8-10.
- Tree stumps removed along segment 7 (Photo 1).
- Several rips and broken stakes in the silt fence along segment 7 (Photo 2).
- Several broken stakes in the silt fence along segment 11 (Photo 3).
- Several broken stakes and rips in the silt fence along segment 12 (Photo 4).
- Several rips in the silt fence along segment 13 (Photo 5).
- Rip in the silt fence along segment 14 (Photo 6).

Action Items:

1. Repair silt fence as noted above.

my Poh

Date: 11/15/24

Inspector's signature:

Jeffrey Polidor Survey-GIS Technician

Distribution:

Town:

Epsilon Associates: Horsley Witten Group: Lori Capone Shawna Risotti Adam Burney Marc Bergeron Janet Carter Bernardo, P.E. Jeffrey Polidor

caponel@sudbury.ma.us RisottiS@sudbury.ma.us burneya@sudbury.ma.us mbergeron@epsilonassociates.com jbernardo@horsleywitten.com jolidor@horsleywitten.com

PHOTOS:



Photo 1: Tree stumps removed along segment 7. Photo taken on 11/15/24

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 One Turks Head Place, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600 Phone: (857) 263-8193 Phone: (401) 272-1717 Phone: (603) 658-1660



Photo 2: Rip in the silt fence along segment 7. Photo taken on 11/15/24



Photo 3: Broken stakes in the silt fence along segment 11. Photo taken on 11/15/24

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 One Turks Head Place, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600 Phone: (857) 263-8193 Phone: (401) 272-1717 Phone: (603) 658-1660



Photo 4: Broken stakes and rip in the silt fence along segment 12. Photo taken on 11/15/24



Photo 5: Rip in the silt fence along segment 13. Photo taken on 11/15/24.

Horsley Witten Group, Inc. 90 Route 6A, Sandwich, MA 02563 112 Water Street, 6th Floor, Boston, MA 02109 One Turks Head Place, Suite 300, Providence, RI 02903 113 R2 Water Street, Exeter, NH, 03833

Phone: (508) 833-6600 Phone: (857) 263-8193 Phone: (401) 272-1717 Phone: (603) 658-1660



Photo 6: Rip in the silt fence along segment 14. Photo taken on 11/15/24.