

Photography Log

PROJECT NUMBER

12970.00

CLIENT

Massachusetts Department of Conservation and Recreation

251 Causeway Street, #900

Boston, MA 02114

NSTAR Electric Company d/b/a Eversource Energy

247 Station Drive

Westwood, MA 02090

LOCATION

Bridge 127 (Hop Brook)

Sudbury, Massachusetts



NO. 1 / 2.26.2018 12:30 PM

DESCRIPTION

Bridge facing east



NO. 2 / 6.12.2017 11:43 AM

DESCRIPTION

Bridge facing west



NO. 3 / 2.26.2018 12:34 PM

DESCRIPTION

North side of bridge



NO. 4 / 9.22.2017 9:23 AM

DESCRIPTION

Northwest abutment



NO. 5 / 2.26.2018 12:38 PM

DESCRIPTION

Northeast abutment



NO. 6 / 9.22.2017 8:36 AM

DESCRIPTION

Plate girder - north side



NO. 7 / 2.26.2018 12:31 PM

DESCRIPTION

South side of bridge



NO. 8 / 9.22.2017 9:21 AM

DESCRIPTION

Southwest abutment



NO. 9 / 9.22.2017 9:24 AM

DESCRIPTION

Southeast abutment



NO. 10 / 9.22.2017 9:20 AM

DESCRIPTION

Plate girder - south side



NO. 11 / 9.22.2017 9:58 AM

DESCRIPTION

Inside girders facing east



NO. 12 / 9.22.2017 9:57 AM

DESCRIPTION

Inside girders facing west

Photography Log

PROJECT NUMBER

12970.00

CLIENT

Massachusetts Department of Conservation and Recreation

251 Causeway Street, #900

Boston, MA 02114

NSTAR Electric Company d/b/a Eversource Energy

247 Station Drive

Westwood, MA 02090

LOCATION

Bridge 128 (Hop Brook)

Sudbury, Massachusetts



NO. 1 /

DESCRIPTION

01 Bridge facing east.jpg



NO. 2 / 7.26.2019 11:42 AM

DESCRIPTION

Bridge facing east



NO. 3 / 7.26.2019 11:41 AM

DESCRIPTION

Bridge facing west



NO. 4 / 9.21.2017 1:41 PM

DESCRIPTION

Northwest abutment



NO. 5 / 9.21.2017 1:40 PM

DESCRIPTION

Northwest abutment



NO. 6 / 9.21.2017 1:40 PM

DESCRIPTION

West abutment



NO. 7 / 9.21.2017 1:40 PM

DESCRIPTION

Southwest abutment



NO. 8 / 9.21.2017 1:40 PM

DESCRIPTION

Southwest abutment



NO. 9 / 9.21.2017 1:40 PM

DESCRIPTION

Southwest abutment



NO. 10 / 9.21.2017 1:53 PM

DESCRIPTION

Plate girder - south side



NO. 11 / 9.21.2017 2:12 PM

DESCRIPTION

Plate girder - south side



NO. 12 / 9.21.2017 12:43 PM

DESCRIPTION

Inside plate girders



NO. 13 / 9.21.2017 2:11 PM

DESCRIPTION

Plate girder - north side



NO. 14 / 9.21.2017 2:10 PM

DESCRIPTION

Plate girder - north side



NO. 15 / 9.21.2017 2:10 PM

DESCRIPTION

Northeast abutment



NO. 16 / 9.21.2017 2:10 PM

DESCRIPTION

Northeast abutment



NO. 17 / 9.21.2017 2:10 PM

DESCRIPTION

Northeast abutment



NO. 18 / 9.21.2017 2:09 PM

DESCRIPTION

East abutment



NO. 19 / 9.21.2017 2:09 PM

DESCRIPTION

East abutment



NO. 20 / 9.21.2017 2:09 PM

DESCRIPTION

Southeast abutment



NO. 21 / 9.21.2017 2:09 PM

DESCRIPTION

Southeast abutment



NO. 22 / 9.21.2017 2:08 PM

DESCRIPTION

Southeast abutment